

The Printer Could Not Connect To Web Services

Are you dealing with the annoying “printer could not connect to web services” error when using your HP printer’s internet-enabled features? You’re not alone! Many HP printer users are experiencing this issue every day. Don’t worry, though. There are some workarounds that you can take to help resolve this error and get your printer back in action. Keep reading to discover how you can fix the “printer could not connect to web services” error and get your printer working again.




Printer Could Not Connect To Web Services – Fixed

When your HP printer fails to connect to Web Services, you will receive one of the following error messages, either on your printer or computer screen:

- Server connection error.
- Web Service Problem
- Service connection error.


Tap or click OK on the error message screen. Are you new to troubleshooting? Is this your first time experiencing a web services issue with your HP printer? We understand it can be daunting, but don't worry. Try these solutions one by one, and you'll be able to connect your printer to Web Services again in no time.



#1 Check For A Web Service


HP's web services provide a comprehensive suite of tools and solutions to help create and manage a successful online presence. However, this awesome service is only supported by some HP printers. So, first, check if your HP printer supports Web Services. If not, you can end this conversation here. Or else, try the next solution. Do you want to know if your HP printer supports Web Services? Check out these easy steps to find out!

- Turn on your printer and look for a “Web Services” or “ePrint” icon on the control panel.
- If you find the icon, your printer is supported.
- If you don't, your printer isn't supported.
- Still not sure? Take a look at your printer's mobile printing solutions for more information.



Check The Connection Status


- A stable and active internet connection is important for smooth experiences with HP's web services.
- So, verify if you have connected your printer to a stable internet connection via wireless or wired (Ethernet cable). If not, connect it.
- Ensure that you have connected the printer to a compatible network type.



For Wireless

- Check if the Wi-Fi feature is enabled on your printer.
- To do so, open the printer's Wireless Network menu or Settings menu.

- Need help? Look for and tap on the Wi-Fi icon on your printer's control panel.
- This will open the Wireless Summary screen.
- Alternatively, verify if the printer's Wi-Fi light is solid; if it is, the feature is enabled.



For Ethernet

- Make sure you have connected the Ethernet cable directly from your printer to the network device and that your computer is connected to the same network over a wireless or wired connection.


*Important Note: Make sure you have hooked up your **HP printer** directly to the network to use the Web Services feature. Connecting to a guest or host network won't work. Now, check if the printer is connecting to Web Services. If the same issue persists, take it with a grain of salt. Try the next solution to fix it.

#3 Reboot The Devices

If you're having connectivity issues, why not give restarting your devices a try? It might help you out!


- Restart your computer (on which you have installed and are accessing the printer), the printer, and your wireless router.
- After that, try to connect the printer to Web services.

If the printer is not connecting to Web Services again, verify and enable the Web Services feature manually.



#4 Enable Web Services

- First, print your printer's network configuration page. (Contact us for more details).
- Secondly, tap on the HP ePrint icon on your printer's control panel.
- If there is no HP ePrint icon available, go to your printer's Wireless Settings screen and tap on the Web Services option.
- Now, if the screen prompts you to set up HP ePrint or enable Web Services, follow the on-screen instructions to do it.
- After that, try to connect your printer to Web Services.



End Note

Hopefully, the solutions above helped you fix “The printer could not connect to Web Services” issue. Reach out to us if you need real-time assistance in fixing the issue.